



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
August 11, 2009

Reviewed: LR

Mine Name: Golden/Lucky Chantz	Permit Number: S0370064
Operator Name: Dan Shumway	Inspection Date: June 3, 2009
Inspector(s): Wayne Western	Time: 12:30 pm 1:30 pm
Other Participants: Ted McDougall	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount:

Held by BLM

Permit fee:

Not paid since 2006.

Directions:

The site is accessed by turning off US 191 at the Recapture Dam. The gate was not lock during the inspection.

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The site is inactive. Ted McDougall told me that the Permittee wants to close the site and apply for bond release, which the BLM holds.

Much of the equipment has been removed from the site. There is still equipment that must be removed from the site and a loading ramp that needs to be removed.

Much of the site is in a canyon bottom that periodically gets flooded. Ted McDougall told me that much of the disturbed area has been revegetated.

The remaining work needed for bond release is grading the loading area and removing material from the site. The road to the site will be left as part of the post mining land use.

Conclusions and Recommendations:

The Division will work with the BLM to have the site reclaimed. The Division will let the BLM take the lead for bond release because they hold the bond.


Inspector's Signature

whw

cc: Dan Shumway

Ted McDougall BLM

O:\M037-SanJuan\S0370064-Golden-LuckyChance\inspections\ins_06032009.doc



8/19/2009



Ted next to trammel



Loading area with sluice equipment





On top



Top of loading area



Misc. equipment

